

Curso Eléctrico

Palas P&H 4100XPC

Codelco Andina.

Entendiendo el Concepto de
Seguridad



Seguridad en el Equipo

NOTA


SEGURIDAD PRIMERO

PRECAUCIÓN

 **PRECAUCIÓN**

 **ADVERTENCIA**

 **PELIGRO**



 CAUTION	
	<p>Opening door stops machine.</p> <p>unexpected stopping or abnormal performance can cause personal injury and property damage.</p> <p>Do not open doors when machine is running.</p>



Seguridad en el Equipo

⚠ WARNING	
	
<p>ROTATING PARTS AND HAZARDOUS VOLTAGE INSIDE. CAN CAUSE SEVERE INJURY OR DEATH. Keep fingers clear of rotating machinery. Disconnect power to all circuits before opening covers. Use lockout and tagout procedures before servicing.</p>	

R4219001

⚠ WARNING	
	<p>HAZARDOUS VOLTAGE INSIDE.</p> <p>CAN CAUSE SEVERE INJURY OR DEATH.</p> <p>Keep all doors and covers closed.</p> <p>Do not open unless qualified and authorized.</p> <p>Disconnect power to all circuits.</p> <p>Use lockout and tagout procedures before servicing.</p>

301157

⚠ DANGER

<p>HAZARDOUS VOLTAGE. WILL CAUSE SEVERE INJURY OR DEATH.</p> <p>Disconnect tail cable voltage and lock supply switch open.</p> <p>Remove tail cable from machine.</p> <p>Insure that all high voltage is removed from the machine before servicing switch.</p>

301158

NOTICE	
<table border="1"> <tr> <td style="text-align: center;"> V SEE 3201805D_ </td> </tr> </table> <p style="font-size: 2em; font-weight: bold; margin-top: 10px;">VOLTS</p> <p style="margin-top: 20px;">MAXIMUM LEVEL MAY BE PRESENT</p>	V SEE 3201805D_
V SEE 3201805D_	

3201780D_

